



GUNDRILLING

WEBINAR

JULY 31ST


SAVE YOUR SEAT


Contact us at:

Mark Wheatley
Application Specialist
Drill Masters Eldorado Tool, Inc.
248-613-1339
[**mwheatley@dmtool.com**](mailto:mwheatley@dmtool.com)

Phil Fassnacht
VP Sales & Marketing
M4 Sciences LLC
765-588-7001
[**fassnachtp@m4sciences.com**](mailto:fassnachtp@m4sciences.com)

Accuracy Precision Quality





THE GUNDRILLING HANDBOOK

L. C. KETTER

4TH. EDITION


Gundrilled parts









Crank shaft





Accelerated main shaft




Piston




Cylinder block




Connecting rod




Connecting rod (SCM-21)




Master cylinder




Nozzle





Plastic mold



Heat exchanger (carbon)





Piston




Gundrill Machines

Gundrill Machines are designed to provide optimum conditions for gundrill operation; the gundrilling machine's high pressure pump delivers lubricant to the rear of the drill. The drill can be driven by the spindle or be held stationary if the work piece is rotated. During drilling, the work piece can be advanced or the drill can advance. The gundrill is supported by *anti-whip devices* along the shank and at the rear of the chip box. The chip box contains *chip deflectors* and a front end bushing, which guides the drill into the work piece. The chip box also contains escaping chips and lubricant, which are separated and filtered.








Tools (Gun drill Gun reamer)


Gun Drills and Gun Reamers

As deep hole drills, ours are highly efficient tools assuring "deeper", "faster", and "more accurate" drilling compared with twist drills.


Gundrills






Gunreamers



Specifications of gun drill



Names at the tip of a gundrill




Recommended form of cutting edge

Drilled material	α°	β°	Drilled material	α°	β°
Low carbon steel	30	20	Cast iron	15	20
Carbon steel	30	20	Aluminum alloy	15	20
Alloy steel	30	20	Stainless steel	30	20

Driver dimensions (inches)

Drill diameter $D \phi$	$D1 \phi$
0.0781 to 0.12	1/2
0.125 to 0.5	3/4
0.5156 to 0.75	1.0
0.7656 to 1.0	1 1/4
1.0625 to 1.5	1 1/2




Coolant Hole Configurations


Coolant hole configurations play a critical part in the gundrill selection process. Coolant systems that lack adequate pressure or volume would benefit from the single oil hole. The single orifice allows more PSI with less volume. Systems with ideal PSI and GPM should run either a Kidney (.075" – .3174") or Dual (.3108" – 1.520") oil holes for greater chip evacuation and coolant to the cutting edge.




Single



Kidney



Dual




Twin Flute

Backtapers


Backtapers are a linear reduction in the tool diameter allowing for clearance and minimal friction. Standard backtaper, .0008" – .0010" per inch, is generally used in steel applications where the heat generated by the bearing pads (contours) does not expand and contract the hole during the drilling process. Materials that heat and cool quickly such as aluminums, cast iron, etc. require increased backtaper to prevent the hole from closing in on the gundrill during the retract mode.

DIAMETRICAL BACKTAPER



Objects enhanced for visual representation

TOOL WEAR GUIDE




CONDITION	CAUSE
Wear -	
A. Cratering	RPM low or feedrate high
B. Corner breakdown	Heat: RPM high or coolant flow
C. Built up edge	Wrong coolant
D. Pickup on margin	Wrong coolant
E. Wear on margin	Misalignment
F. Burn on outside angle	Too high RPM, coolant flow
G. Chipping-	
G-1 Point	Point bumped
G-2 Outside corner	Bumped, or trapped chip
G-3 Outside angle	High feedrate & end pressure
G-4 Outer edge	Rubbing on tight bushing
G-5 Shoulder	Bumped, or tight bushing


How To Determine If Time To Grind Determining Time to Re-Grind

Determining when a tool has reached the point when it's time to re-sharpen takes a visual examination of the cutting edge. Inspecting the cutting edge will determine if the running parameters are adequate for optimal results.


TOOL TO BE RESHARPENED
IF MARGIN WEAR MEETS OR
EXCEEDS $\frac{1}{2}$ - $\frac{2}{3}$'s THE FULL
DISTANCE OF THE MARGIN





This drawing is an example of when it's time to re-grind a tool. Pay close attention to the margin, smearing, or a need to be cleaned-up during the re-grind process to ensure the tools' repeatability.




If the outside corner is rounded, it usually means that the SFM is too high and the RPM should be lowered in 10% increments until the wear is along the cutting edge and the corner remains pristine.



**If there is evidence of chipping or cratering along the cutting edge point,
the feed rate should be lowered.**



If there is build-up on the OD, it is usually a result of too much heat due to low lubricity. Often seen in water soluble applications.



- * COOLANT CONCENTRATION TOO LOW
- * POOR LUBRICITY

How to troubleshoot gundrilling problems:

A detailed troubleshooting guide, found in the literature of all gundrill and gundrill machine manufacturers, is a great place to start. They are often divided into hole faults or tool faults. Find your problem on the chart and address each area of concern and check and correct any non compliant issues. Most of the remedies from these troubleshooting guides can be attributed to something not correct with the set up and an ignoring of a salient issue which might be causing everything to go wrong. Many times, it is just one thing. Therefore, one adjustment, and you are back to drilling repeatable and predictable outcomes.

Quickly, let's review some of those fundamentals

Machine Requirements for Successful Gundrilling:


Proper alignment (newer gundrill machines and most all CNC are great) For a gundrill operation to have the best chance for the straightest hole, the deviation between the spindle and the bushing, which is actually between the spindle and back of the chip box should not be more than $+.0005''$. When using CNC, a pilot hole is produced to within the same tolerance as the gundrill bushing, $-.0000 + .0002''$. This alignment on CNC is assured, however, over time, a gundrill machine may need to be adjusted to return the spindle to a dead center, zero, position.

Information for Use of Gun Drills


Machines and precision

To demonstrate the performance of a gun drill effectively and sufficiently, "precision of the machine and equipments" plays an important role.

- 1) A highly rigid special machine with low vibration should be used.
- 2) High precision should be secured with the machine and the bush, as shown in the table on the right.
- 3) Irregular feed causes breakage, and automatic mechanical feed is the best for gun drilling.
- 4) Sufficient power is required to allow high speed rotation.
- 5) To prevent breakage, a safety device for torque over check must be provided.



		in mm
Check item	Illustration for measurement	Tolerance
a Deviation of spindle		≤ 0.005
b Clearance between spindle hole and driver		$(d - d') \leq 0.013$
c Clearance between drill bush and drill outer diameter		$(d - d') \leq 0.015$
d Concentricity between spindle and bush		≤ 0.013
e Parallelism between spindle and bush hole in table travel		$\leq 0.005/$




Machine configuration

Proper whip guide placement

Again charts are available to determine the maximum unsupported tool length. RPM's higher than allowed for the distance where the flute is running unsupported will result in 'ballooning' of the flute and drill failure. Proper whip guides, gizmos, drill guides, chip deflectors, all become critical to the stabilization of the precision drill trying to do its job.

Proper whip guide set up.



Proper coolant pressure for the diameter

Coolant pressure requirements are also standard and are on many charts through the industry. It is highly recommended that you adhere to these setting if at all possible. A gundrill machine will be adjustable. A 1/4" drill should run at 925 to deliver the required 2.2 GPM for proper lubrication. The same machine needs to be able to also deliver 400 PSI for the 3/4" diameter and 8.4 GPM. When PSI does not not changed when diameter changes, trouble.

- STARTING SURFACE FEET PER MINUTE -

LOW & MED. CARBON STEEL	TOOL STEELS	HI-TEMP. ALLOYS
Rc SFM	Rc SFM	(Nickel Based)
12-17 330	17-22 250	Rc SFM
17-22 280	22-27 200	12-22 120
22-27 230	27-32 150	22-32 90
27-32 180	32-37 100	32-42 60
32-37 130		(Cobalt Base:
37-42 80	CAST IRON (Grey)	-40%; Iron Base:
	Rc SFM	+20%)
	12-17 400	
ALLOY STEEL	17-22 350	COPPER (PURE)
(4000, 5000, 8000 Series)	22-27 300	Rc SFM
Rc SFM	27-32 250	- 250/275
17-22 280	(W/Free Carbides:	
22-27 230	-50%; Ni-Resist:	COPPER ALLOYS
27-32 180	-60%)	(Beryl, Ni-Based)
32-37 130		Rc SFM
37-42 80	CAST IRON	12-22 200
	(Nodular)	22-32 130
	Rc SFM	32-37 60
STAINLESS	12-17 300	
(300 Ser & PH)	17-22 250	ALUMINUM, CAST
Rc SFM	22-27 200	& 2024
12-17 230	27-32 150	Rc SFM
17-22 200	32-37 100	- 600
22-27 170	(Ni-Resist & Ductile:	
27-32 140	-50%)	ALUMINUM,
32-37 110		WROUGHT
37-42 80	TITANIUM ALLOY	(7075, 6061 etc.)
	(Ti6Al4V, etc.)	Rc SFM
STAINLESS	Rc SFM	- 550
(400 Series)	12-17 260	
Rc SFM	17-22 220	SINTERED MATL,
12-17 280	22-27 180	PLASTIC, WOOD,
17-22 240	27-32 140	GRAPHITE- See
22-27 200	32-37 100	notes, pages 8-4 &
27-32 160	37-42 60	8-5.
32-37 120		
37-42 80	BRASS, BRONZE,	
Free Mach: +30%	MAGNESIUM	
	Rc SFM	
	- 550	

**COOLANT PRESSURE, FLOW RATES
and
UNSUPPORTED SHANK LENGTH**

Note: Please read important notes following table.

Drill Dia. (In.)	Pressure (PSI)	Flow Rate (GPM)	Max. Unsup. Shank (In.)	
			High SFM	Low SFM
.0550	2000 +	0.2	1	4
.0780	1800	0.3	2	6
.1250	1500	0.7	3	8
.1560	1300	1.1	4	10
.1875	1150	1.5	6	12
.2190	1050	1.9	7	14
.2500	925	2.2	8	16
.2810	850	2.6	9	18
.3125	775	3.0	10	20
.3440	725	3.4	11	22
.3750	675	3.8	12	24
.4375	600	4.5	14	28
.5000	525	5.3	16	32
.5625	500	6.1	18	36
.6250	450	6.8	20	40
.6875	425	7.6	22	44
.7500	400	8.4	24	48
.8750	350	9.9	28	56
1.000	325	11.4	32	64
1.125	300	12.9	36	72
1.250	275	14.5	40	80
1.375	250	16.0	44	88
1.500	225	17.5	48	97

Proper coolant type

Gundrilling oil is a special blend. The old White and Bagley and the old Eldorado (now Master Chemical and Drill Masters Eldorado) developed together a gundrilling oil formula that is still an industry standard today. Most oil manufactures have the 2190 formula providing you the opportunity to buy your oil from whomever you get the rest of your coolants from. Water soluble is a different subject. Some are better than others but the most effective use is when there is a 10%-12% ratio. Most common problem with water soluble is galling as the lubricity tends to give out or never is enough to begin with.


Proper geometry for the material and the application

Though the industry standard geometry N8 is used in most applications benefits can be derived by a different set of geometries not only for different materials but also for different results and or complexity of the application. Examples of each might be Aluminum (N4) and cast irons (N73) and again with the N73 for stack material or angle entry.


Nose Grinds

Standard, general purpose nose grinds, N-8 & Facet, are supplied on our stock gundrills. Special grinds are applied to obtain better chip control, bottom forming, and heavy feed rates when drilling Aluminums and Cast Irons in conjunction with special contours.


Some special grinds may be dictated by part print calling and for corner radius, full spherical radius, flat bottom, step drills, pilot non-cutting step drills, chip breakers, etc.




N-8




N-4




N-73




Facet (F-8)




N-8+35



N-4+35



N-126




COPPER

Proper filtration of the coolant

No less than a 20 micron final filter but preferably 5. Gundrill machine manufactures employ at least a three stage filtration process, starting with 50-100 then down to 25 and final stage being the 5 micron. Any contaminant smaller than 5 micron will pass between the OD of the drill and the wall of the material being drilled, resulting in no scoring or lapping of material.


Relief Depths

Relief depths are undercuts placed in specified locations to allow coolant to lubricate the bearing pads therefore cooling the tool and obtaining optimal surface finishes. The depths of the reliefs are manufacturing standards and sometimes increased depending on the application.



Contours

- R-1** **Standard contour. Non-Micable. Main use is for holes that do not crossover or intersect.**
- R-1A** **Pad break allows for more coolant flow if pumping system is not able to produce high pressures.**
- R-2** **The trailing pad adds stability and can improve straightness. Caution, high temp alloys can contract slightly while being drilled.**
- R-3** **Micable. More support and stability than an R1. Better surface finish, less drift. Good for interrupted cuts and cross holes. Nickel alloys do not react well to this contour.**
- R-4** **Cast iron, Aluminum. Good to use when opening a hole.**



Proper speed and feed for the material

Again, charts of all kinds are available to give you the starting points for any material. The best ones are charts that correlate SFM to hardness. 40 Rockwell D2 tool Steel must have a slower SFM than the same D2 at 26 Rc. Drill chipping, premature edge wear, or material buildup can occur when the SFM is off by even a few hundred RPM. Materials have speed limits, some more than others. Another chart to attack high temperature alloys is one that relates SFM to the % to a particular element found the metal. The most common of these 'nasty' elements are Chromium and Nickel. Let's look again at the elements chart.

RECOMMENDED FEED AND SPEED CHARTS ASSUME PROPER GUNDRILLING PROCESSES
VALUES BELOW ARE DESIGNED TO YIELD THE MAXIMUM NUMBER OF CYCLES WITH THE HIGHEST QUALITY HOLE
FASTER SPEEDS AND FEEDS ARE ACHIEVABLE, HOWEVER, CYCLES AND HOLE QUALITY MAY BE COMPROMISED

Tool Steels D,S,M,O,H,P Series			Cast Iron - Ductile			Cast Iron - Grey		
Bhn	Rc	SFM	Bhn	Rc	SFM	Bhn	Rc	SFM
175-225	< 19	250	125-175	< 19	300	125-175	<19	400
225-275	19-28	200	175-225	19-28	250	175-225	19-28	350
275-325	28-35	150	225-275	28-35	200	225-275	28-35	300
325-375	35-40	100	275-325	35-40	150	275-325	35-40	250
			325-375	35-40	100	With Free Carbides -50%		
Steel, Low, Medium Carbon C1010-1550			Ductile Ni Resist -50%			Ni Resist -60%		
			Alloy Steels 4000,5000,8000 Series			Titanium Most Grades		
Bhn	Rc	SFM	Bhn	Rc	SFM	Bhn	Rc	SFM
125-175	< 19	450	175-225	< 19	350	125-175	< 19	260
175-225	19-28	400	225-275	19-28	300	175-225	19-28	220
225-275	28-35	350	275-325	28-35	250	225-275	28-35	180
275-325	35-40	300	325-375	35-40	200	275-325	35-40	140
325-375	40-45	250	375-425	40-45	150	325-375	40-45	100
375-425		200				375-425		60
Stainless Steel* 400 Series			Stainless Steel* 300 Series + PH			High Temp Alloy Nickel Based		
Bhn	Rc	SFM	Bhn	Rc	SFM	Bhn	Rc	SFM
125-175	< 19	280	125-175	< 19	230	125-225	< 19	120
175-225	19-28	240	175-225	19-28	200	225-325	19-35	90
225-275	28-35	200	225-275	28-35	170	325-425	35-45	60
275-325	35-40	160	275-325	35-40	140	Cobalt Based -40%		
325-375	40-45	120	325-375	40-45	110	Iron Based +20%		
375-425		80	375-425		80			
* Free Machining +30%			* Free Machining +30%			CAUTION ! Gundrills must always be piloted or bushed when rotating except at the lowest of speeds.		
Copper Alloys Beryllium, Nickel Based			Aluminum Alloys, Free Chipping Brass, Magnesium, Soft Copper					
Bhn	Rc	SFM	SFM					
125-225	< 19	200	600-700					
225-325	19-35	130						
325-375	35-40	60						
Please consult your DME application specialist for assistance.								

APPROXIMATE FEED RATES (IN/REV)								
Diameter mm	Inch	Steel Carbon Low, Med	Steel Alloy Tool, 400 SS	Stainless 300 Series	Copper/ Titanium/ High Temp Alloy	Aluminum FC Cast Iron Grey	Cast Iron Ductile	Aluminum Soft Copper
1	0.039	0.00007	0.00007	0.00007	0.00005	0.00008	0.00008	0.00005
1.9	0.075	0.00011	0.00011	0.00011	0.00008	0.00011	0.00011	0.00008
2.54	0.1	0.00015	0.00015	0.00015	0.0001	0.00015	0.00015	0.0001
4.75	0.187	0.0003	0.0003	0.0003	0.0002	0.0003	0.0003	0.0002
6.35	0.25	0.00045	0.00045	0.00045	0.0003	0.0005	0.0005	0.0003
9.525	0.375	0.0007	0.0006	0.0006	0.0005	0.0013	0.001	0.0005
12.7	0.5	0.0008	0.0007	0.0006	0.0002	0.002	0.0015	0.0007
15.8	0.625	0.001	0.00085	0.0007	0.0007	0.0025	0.002	0.00085
19.05	0.75	0.0013	0.001	0.0008	0.0008	0.003	0.0025	0.001
25.4	1	0.0018	0.0015	0.001	0.001	0.004	0.003	0.0015
31.75	1.25 +	0.0023	0.002	0.0012	0.0012	0.005	0.0035	0.002

Parameters by Chemistry Single Flute Gundrill

Use these charts when parameters cannot be found in any reference source, but the chemistry of the material is known.

%	Speed (Surface Ft./Minute)																			
	Al	C	(Cb)	(Co)	(Cr)	Cu	Fe	Mg	Mn	(Mo)	(Ni)	Pb	Si	Sn	(Ta)	(Ti)	(V)	(W)	Zn	Zr
0.2	-	375	-	300	300	-	-	600	450	375	-	450	-	600	90	90	300	-	600	*
0.5	-	300	-	300	300	-	-	600	375	300	-	450	-	600	90	90	240	240	600	*
1.0	-	240	120	225	270	-	-	600	300	225	-	450	*	600	90	90	210	210	600	*
2.0	-	195	90	180	240	-	90	600	225	195	225	450	*	450	90	90	150	180	600	*
4.0	150	150	90	150	210	-	105	600	180	150	150	450	*	450	75	90	120	150	600	150
8.0	300	-	75	-	180	150	120	-	150	120	120	600	*	375	75	-	90	90	600	120
10.0	300	-	-	-	120	225	135	-	120	105	105	600	*	300	75	-	75	75	600	-
32.0	450	-	-	-	90	300	150	-	-	90	90	-	-	-	-	-	-	75	600	-
64.0	600	-	-	-	75	600	225	-	-	-	75	-	-	-	-	150	-	-	-	-
100.0	600	-	-	-	-	600	450	-	-	-	75	-	-	-	-	120	-	-	-	-

Legend:

Al= Aluminum C= Carbon Cb= Columbium Co= Cobalt Cr= Chromium Cu= Copper Fe= Iron
Mg= Magnesium Mn= Manganese Mo= Molybdenum Ni= Nickel Pb= Lead Si= Silicon Sn= Tin
Ta= Tantalum Ti= Titanium V= Vanadium W= Tungsten Zn= Zinc Zr= Zirconium

Note:

1. The starting SFM will be the value from the above chart matching the material's element percentage, then picking the lowest applicable SFM from all the elements. Pay particular attention to the toughest elements, which are bracketed ().

2. Materials around 30 Rc, reduce SFM by 20%; over 30 Rc, reduce SFM by 33%.


Diameter	Feed (Inches/Rev.)	
	With ()	Without ()
.125 - .156	.00010 - .00025	.00020 - .00040
.156 - .250	.00025 - .00050	.00040 - .00100
.250 - .500	.00050 - .00100	.00100 - .00150
.500 - .750	.00100 - .00150	.00150 - .00200
.750 - 1.00	.00150 - .00200	.00200 - .00250
1.00 - 1.50	.00200 - .00250	.00250 - .00300

Some of the following tricks may seem obvious. On the other hand, there are sure to be a few that just haven't occurred to you yet.

Siamese holes— Drill the first hole, then plug it with a rod (preferably made from the same material as the workpiece; definitely not from a material which is more difficult to drill).

The rod doesn't have to be a press fit, but it should be of a diameter which will drag in the hole as it is being inserted. Sequence of drilling (large hole as opposed to small hole first) is not critical.

The plug can normally be rotated and reused a few to several times depending on fit in the hole as succeeding portions are drilled away.




Intersecting holes—

1. Breaking into a previously drilled hole (on center) with a smaller hole is usually not a problem.

2. If the smaller hole continues into the far wall of the larger hole, plug as described in 'A.' above.

3. In all cases where one hole intersects another off-center, plug the first hole. Even if a large hole is breaking into a previously drilled small hole, the interrupted cut can give you trouble.



Producing chips that do not become so long as to clog the chip box

In some cases the proper feed and speed that produces the most linear inches and the highest quality hole in regard to size and finish will produce chips that become long and even ribbon like. These can clog chip boxes, shutting down spindles with torque meters or breaking drills with those without. 1000 series low carbon steels come to mind. Chip breakers, dwells, or if you are drilling from 1mm to 12mm, incorporating a TriboMAM unit developed by M4 sciences (Nice product placement there) may be an answer.

Proper contour for the desired results

Examples of how the contour burnishes the hole and what the different pads can do on any particular application. At this point we are really tweaking an application finding the best position of these guide pads to achieve or the required tolerance.